

BLUE SIDE UP!



The BFC, founded in 1956, meets at Naper Aero Estates (LL10), a private residential airport in Naperville, Illinois. Monthly meetings are held at the airport in the clubhouse near the South end of the runway on the first Tuesday of every month beginning at 7:30 PM. The Club has 45 equity members sharing three planes.

ERV - CIP

LL10 Avgas 100LL

\$6.52/gal as of Sept. 2026

Aircraft Rates

C172S	4BC	\$144.70
C172SP	3SP	\$138.70
C182T	89L	\$179.52

CY Cumulative Hours Flown

August 2026

884BC	17.8 hrs.
983SP	24.5 hrs.
1489L	0.6 hrs.
TOTAL	42.9 hrs.

2026 Totals

884BC	158.4 hrs.
983SP	182.7 hrs.
1489L	95.6 hrs.
TOTAL	436.7 hrs.

IN THIS ISSUE...

September Meeting Minutes

MEETING MINUTES

The BFC held its monthly meeting on Tuesday, September 1st, 2026 at Naper Aero. The President called the meeting to order at 7:30 PM.

The minutes from the last meeting were published in the newsletter. The minutes were approved as published.

The Treasurer's report was reviewed for the members. Total flying time for August 2026 was 42.9 hours with 1.0 hour club time. We made \$19,103.18 in payments and had \$11,439.56 in billings. Cash in the bank is \$158,628.11. Further details follow in the newsletter. The Treasurer's report was approved as presented.

The aircraft reports were presented by the plane captains and maintenance officer. Old and new business items were presented. Please see details in the following sections.

The meeting adjourned at 8:27 PM.

Join us for our next meeting:

Tuesday, October 6th, 2026

Business meeting @ 7:30pm

Details to follow via email.

See you there!

Attendees**Members**

Kevin Kanarski
 Ray Kvietkus
 Pashupati Pandey
 Jeff Krischel
 Nick Davis
 Kris Queen
 George Schick
 Al Loek
 Don Patterson
 Walt Slazyk
 Jack Lindquist
 Jim Krzyewski
 John Sheskier
 Bill Samatas
 Cliff Kotchka
 Patrick Pyszka

Guests

Wyatt B.
 Jim B.
 Bo C.
 Louis W.
 Chris S.
 Vince L.

Social

TREASURER'S REPORT

I. AIRCRAFT DATA

	<u>884BC</u>	<u>983SP</u>	<u>1489L</u>
BEGIN TACH	4,343.9	7,037.8	2,354.8
END TACH	4,361.7	7,062.3	2,355.4
TOTAL HOURS	17.8	24.5	0.6
TBO	2,000	2,000	2,000
TMOH	(201)	(511)	1,606

II. MONTHLY BILLING SUMMARY

	<u>884BC</u>	<u>983SP</u>	<u>1489L</u>	<u>TOTAL</u>
TOTAL HOURS	17.8	24.5	0.6	42.9
LESS: CLUB TIME	(0.50)	-	(0.50)	(1.0)
BILLABLE HOURS	17.3	24.5	0.1	41.9
BILLING RATE	\$ 140.60	\$ 134.60	\$ 174.48	
FLYING CHARGES (billed)	\$ 2,432.38	\$ 3,297.70	\$ 17.45	\$ 5,747.53
MONTHLY DUES (billed)				\$ 6,885.00
MEMBER CREDITS				\$ (1,192.97)
TOTAL BILLINGS	\$ 2,432.38	\$ 3,297.70	\$ 17.45	\$ 11,439.56

III. MEMBER CREDIT BREAKDOWN

Ray Kvietkus	Fuel Credit	30.00	(6.11)	(183.30)
Walt Slazak	Fuel Credit	16.50	(6.11)	(100.82)
Bill Samantas	Fuel Credit	14.18	(6.11)	(86.64)
Tim Claudon	Fuel Credit	25.08	(6.11)	(153.24)
Patrick Pyszka	Fuel Credit	21.34	(6.11)	(130.39)
Karthick Giri	Fuel Credit	17.33	(6.11)	(105.89)
Grant McElroy	Fuel Credit	10.90	(6.11)	(66.60)
Pash Pandey	Fuel Credit	22.09	(6.11)	(134.97)
Pash Pandey	Fuel Credit	20.94	(6.11)	(127.94)
Pash Pandey	Lyft	1.00	(37.99)	(37.99)
Jake Black	Fuel Credit	10.00	(6.52)	(65.20)
Fuel now \$6.52 on 8/24/26				
TOTAL CREDITS				\$ (1,192.97)

IV. BANK BALANCES

	<u>US BANK SAV</u>	<u>CHASE CHECK</u>	<u>US BANK CHECK</u>	<u>TOTAL</u>
BEGIN BALANCE	\$ 149,016.51	\$ 4,964.74	\$ 111.50	\$ 154,092.75
Operating Cash In		\$ 23,429.81		\$ 23,429.81
Operating Cash Out		\$ (19,103.18)		\$ (19,103.18)
Account Transfers	\$ (3,000.00)	\$ 3,000.00		
Interest	\$ 208.73			\$ 208.73
ENDING BALANCE	\$ 146,225.24	\$ 12,291.37	\$ 111.50	\$ 158,628.11

V. RESERVES			
	BEGIN BAL	INC / (DEC)	END BAL
INSURANCE (\$3200/ mo)	\$ 32,200.00	\$ 3,200.00	\$ 35,400.00
ANNUALS (\$1500/ mo)	\$ 10,500.00	\$ (4,500.00)	\$ 6,000.00
LL10 DUES (\$486/ mo)	\$ 4,860.00	\$ 486.00	\$ 5,346.00
INACTIVE MEMBER	\$ 17,000.00	\$ (4,250.00)	\$ 12,750.00
ENG OVRHL (\$2000/mo)	\$ 54,000.00	\$ 2,000.00	\$ 56,000.00
CREDIT BALANCE MEMBERS	\$ 8,646.76	\$ (153.00)	\$ 8,493.76
FUTURE AIRCRAFT PURCHASES	\$ 10,000.00	\$ 1,000.00	\$ 11,000.00
AIRCRAFT REPAIRS & MAINTENANCE	\$ 16,885.99	\$ 6,752.36	\$ 23,638.35
TOTAL	\$ 154,092.75	\$ 4,535.36	\$ 158,628.11

VI. PAYMENT DETAIL			
Expense	Description	Vendor	Amount
Naper Aero	Fuel	Naper Aero	\$ 6,131.89
	Hangar Fees	Naper Aero	\$ 555.00
	Planning Room Fee	Naper Aero	\$ 225.00
Website Fees	On Line Schedule	Aircraftclubs.com	\$ 36.00
Quickbooks	Acct Software	Intuit	\$ 85.00
Equity Return	Equity	Chris Rorvick	\$ 4,250.00
Garmin GPS	GPS Subscriptions	Kris Knigga	\$ 1,987.00
Keys	Oil Locker Keys	Home Depot	\$ 17.19
Parts	Misc parts	Aircraft Spruce	\$ 303.10
Cookout	August Cookout	Bradley Swanson	\$ 91.25
89L Annual Inspection	Annual Inspection	MTech Aviation	\$ 5,421.75
TOTAL PAYMENTS			\$ 19,103.18

FLYING HOURS

August

884BC	
FLYING	17.8
TACH	4361.7
TBO	2000
TMOH	(201)
†CLUB	0.5
*GAL/HR.	10.2

983SP	
FLYING	24.5
TACH	7062.3
TBO	2000
TMOH	(511)
†CLUB	0.0
*GAL/HR.	10.2

1489L	
FLYING	0.6
TACH	2355.4
TBO	2000
TMOH	1606
†CLUB	0.5
*GAL/HR.	12.3

TBO – engine time between overhauls

TMOH – engine time to major overhaul

† Includes orientation flights

* Gallons per hour for calculating hourly rate. Do not use for flight planning.

AIRCRAFT REPORTS

N983SP

- 1) Zeus fasteners replaced with regular screws in cowling
- 2) Dust cap from fueling nozzle fell in tank; has been retrieved
- 3) **INOP: Pitot heat**
- 4) Propellor needs balancing

N884BC

- 1) One cowl fastener missing
- 2) Reported intermittent fuel gauge inop on startup
- 3) ELT battery due in October
- 4) Pitot-static due in November

N1489L

- 1) Annual inspection was completed:
 - a. Main tires changed
 - b. Avionics master changed
 - c. Pilot top vent repaired
 - d. Elevator tip replaced
 - e. Brake line replaced
 - f. Cleaned the engine of oil
 - g. Propeller hub leaking some oil; not considered an issue yet
 - h. Mags are currently being rebuilt
 - i. **INOP: Autopilot** – suggest not performing autopilot test where pilot tries to override with yoke; this eventually damages the servos

AIRPORT AFFAIRS

John, airport manager, provided updates on the Airport.

Notable ongoing airport issues below:

- Crane activity south of the airport tentatively scheduled for September 8th
- Runway seal coating September 17-19
 - Be on the lookout for prep work happening beforehand
- Storms took a hit on airport systems. The fuel system has been repaired
- South side bushes are shedding thorns which can damage tires; steer clear

OLD BUSINESS

No old business was covered

NEW BUSINESS

Board Member Elections in October

If you’re interested in helping run the club, please get in touch with Kevin. Kevin will be stepping down as president this year, after his 6th year of service to the club. Alex is also interested in taking a break from being the secretary if someone wishes to step up.

SAFETY

Pay attention when fueling planes at a different airport for dust caps on the fuel nozzle. Remove them before fueling.

Pay attention to winds at runway level – they aren't always the same as they are at pattern altitude.

Be aware of humidity because it can degrade aircraft performance.

MEMBERSHIP AND GUESTS

We had several guests at the meeting. There also continues to be a strong entrance list with several applicants regularly attending meetings and 10 applications. Priority is given to applicants in received order that are at the meetings with entrance fee ready.

No openings were available tonight.

Two new guests visited, Louis and Bo.

ACCOMPLISHMENTS

No new accomplishments were reported.



MEMBERS SECTION

This section is for you, the members, to showcase your airplane adventures in the Photo Corner and let others know of your accomplishments. We are also looking for members to submit articles for the newsletter. With the years of flying experience we have in our club, we are looking for members to submit articles in the style of ‘I learned about flying from that’, ‘Never Again’ or ‘Stick and Rudder’. It is in our best interest to make our small community of pilots safer by passing on experience and knowledge. Submit articles to the club secretary.

No article was submitted for this month.

OPERATIONAL & SAFETY REMINDERS

Remember, each of us owns 1/45 of these planes. Adherence to the reminders listed below will keep us safer and help to hold down the cost of maintenance. If you have a problem with a club plane notify the plane captain or maintenance officer before you arrange for any repairs. Let those people decide the best way to have the plane fixed. Phone numbers are in the fuel logbook in the plane.

Oil Dipsticks: DO NOT overtighten. Two fingers, snugged, not torqued down. Overtightening causes us to loosen the oil dipstick housing from the block, resulting in leaks and a repair cost.

Beware of TFR's: Presidential and stadium (Joliet Speedway & Dekalb Univ.).

Windshield cleaning: Use a clean, soft cloth to clean the windshield. Paper towels scratch the soft plastic. Clean rags should be in each plane; more are in the cabinets by 983SP.

Preflight inspection: Use the checklist. It's easy to get distracted and skip important things. When finished, step back and walk around the plane to take in the big picture.

Tire pressure: Check pressure before each flight. If tires are low add air using the red BFC air compressor located in the hangar. Tire gauge is with the compressor. Required PSI for each airplane are listed in the POH and posted in the hangar.

Engine oil: Check the oil change sticker before each flight. If due it's OK to fly, but notify the plane captain or maintenance officer. If you add oil, log it in the fuel logbook. Oil consumption tells us about the health of the engine. Try to add only full quarts.

Nose strut: NEVER, EVER fly with a collapsed nose strut. Remember the sheared rivets in 388ES? That cost a lot to fix.

Bald tires: Bald (no grooves) is OK; cloth showing through the rubber is not. If in doubt roll the plane to check the portion of the tires that you can't see initially.

Closing airplane doors: Please open the window and close the door by gripping the lower windowsill. Opening the window relieves the air pressure as the door comes shut. Gripping the windowsill instead of the door panel handhold prevents expensive damage to the flimsy door panel (like we had on 388ES).

Ground-lean after engine start: Our fuel-injected engines run very rich at low power, which causes the plugs to foul. That results in bad mag checks and the need to have the plugs cleaned. As soon as the engine is running smoothly after start, pull the mixture out a distance of 2 finger widths. Taxi with the engine leaned. It's OK to do the run-up with the engine leaned provided that it runs smoothly. Remember to go to full rich for takeoff.

Runways and patterns at LL10: The preferred calm wind runway is 36. We prefer that you land on the pavement because tire wear is less costly than damage to the gyro instruments due to vibration. When making a right-hand departure, climb to pattern altitude before turning right. Alternatively, make three climbing 90° left turns and cross over the field.

Parking at the fuel pumps: Please be courteous to others. Don't park at the pumps for an extended period of time.

Tow bars: Never leave a tow bar attached to a plane after you are finished moving it. Don't set the tow bar down on the nose wheel pant; remove it.

Finally, if you damage a plane, immediately report it to the plane captain, maintenance office or a board member. You will not be judged (it can happen to anyone), and only those who need to know will hear about it. Our goal is to handle the problem discreetly, efficiently, and get the airplane back in-service ASAP. Thank you.

BFC
P.O. Box 2631
Naperville, IL 60567

inquiry@flybfc.org

ABOUT OUR ORGANIZATION

The BFC, founded in 1956, meets at Naper Aero Estates (LL10), a private residential airpark in Naperville, Illinois. Monthly meetings are held at the airport in the clubhouse near the South end of the runway on the first Tuesday of every month beginning at 7:30PM.

The Club has 45 equity members sharing 3 airplanes:

- 1. 1999 Cessna 172SP N983SP
- 2. 2007 Cessna 172S N884BC
- 3. 2007 Cessna 182T N1489L

Aircraft Reservations: www.aircraftclubs.com
BFC Website: www.flybfc.org

President: Kevin Kanarski
Vice President: Kris Knigga
Secretary: Alex Siegman
Treasurer: Ray Kvietkus
Safety Officer: Nick Davis
Webmaster: Kevin Kanarski
Quartermaster: Jim Krzyzewski
Grillmaster: Bradley Swanson

BFC Instructors:
Nick Davis 630-393-0539
Raymond Kvietkus 630-712-0059 ¹
Sam Darnell 630-577-7953 ²

¹ Available for club checkouts and Flight Reviews
² No C182 training

Chief Maintenance Officer:
John Wrycza 630-697-3559

Plane Captains:
N884BC Don Patterson 815-436-5771
N983SP Jack Lindquist 630-939-1023
N1489L Jim Krzyzewski 630-453-8447